


FIG. 1



Output vectors showing phase errors near a zero-crossing in I:




FIG. 2A

I&Q output components:




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B

2/4

3/4




FIG. 5

4/4




FIG. 6